

TASTE / ODOR ISSUE TROUBLESHOOTING

1. Bad or Plastic Taste

Possible Reason	Solution
Reservoir not flushed properly	If the unit is new, it may need flushing for a longer time.

WL290 Manual Page 61 Revision 9-3-2019